


W211/R230 ABS/SBC TOOL (Repair Code C249F)

Mercedes Benz cars have W211 and R230 with ABS \ SBC system , if using DAS test, the instruction as follows:

TIPS: CODE C249F, OPERATION TIME OF COMPONENT A7/3 IS EXCEEDED (SBC HYDRAULIC UNIT)

The above tips that show internal fault of control unit, you have to replace the SBC control module and using W211/R230 TOOL that can be easily repaired without replace the new control module.

Picture



Testing Show

05/2009 [2009-C4-16] - AddOns: ...;1159;1161;1162;1169;1170;1171;1178;1182;1180;1184;1186;1192;1198;1197;1201;1202;1174;1221 VIN : WDD1714561A001234 Battery voltage: 12.5 V

Vehicle **211.054** Control unit **SBC**

Fault codes

Code	Text	Status
C249F	Check operating time of component A7/3 (SBC hydraulic unit).	CURRENT

www.ecufocus.com

F1 F3 F5 F6 F8 F9 F11

Mercedes Sensotronic brake-by-wire SBC system



Support Type:

BOSCH NR: 0 265 960 012

BOSCH NR: 0 265 960 013

BOSCH NR: 0 265 960 015
BOSCH NR: 0 265 960 018
BOSCH NR: 0 265 960 019
BOSCH NR: 0 265 960 020
BOSCH NR: 0 265 960 023
BOSCH NR: 0 265 960 025
BOSCH NR: 0 265 960 028

Advantage:

- 1, Using the battery without external power supply.
- 2, LCD-screen with instruction , easy operation(From Autofocus)
- 3, Efficient repair, 3 seconds can be repaired successfully.
- 4, Safely instruct version number and repair was successful without any operational risk.