

Fly SVCI 2018 error “The device has been deactivated”

obdii365.com chief engineer offer the solution to Fly SVCI 2018 error “The device has been deactivated” after the software is installed.



Step 1. Exit or uninstall all anti-virus application, then free download the following software to reset.

<https://mega.nz/folder/RfYhBKCS#c0TifR9kvHk0Neg6LdIFkQ>

Step 2. Open “Setting” file to replace the machine serial number and then save it.



Step 3. Run " KeyRecovery_Online", please follow the instruction to operate.

Good luck!

Fly SVCI 2018 tech support: www.obdii365.com